

Oil Field Environmental Incident Summary

Incident: 20160429094434 **Date/Time of Notice:** 04/29/2016 09:44

Responsible Party: Whiting Oil and Gas Corporation

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: ROBINSON LAKE GAS PLANT(WHITING)

Field Name: ROBINSON LAKE

Well File #:

Date Incident: 4/28/2016 **Time Incident:** 15:10 **Facility ID Number:** 550327-01

County: MOUNTRAIL **Twp:** 153 **Rng:** 91 **Sec:** 23 **Qtr:** NW NW

Location Description: Grass fire occurred to the South/South West of the gas plant location and burned approximately 6' by 20'

Submitted By: Brian Wurm

Received By:

Contact Person: Brian Wurm
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.1 Mile

Distance Nearest Water Well: 0.1 Mile

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other						

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 6/13/2016 **Clean Up Concluded:** 6/1/2016

Risk Evaluation:

Grass fire was extinguished by personnel working on location

Areal Extent:

6' by 20'

Potential Environmental Impacts:

Pasture area approximately 6' by 20' burned

Action Taken or Planned:

Personnel working on location extinguished the grass fire using shovels and scrapers.

Wastes Disposal Location:**Agencies Involved:****Updates**

Date: 4/29/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:**Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

According to the report, a pasture area outside of the facility burned due to a fire. Report does not state whether product was released as part of the fire. More follow-up needed.

Date: 5/20/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:**Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

Arrived on location 11:00 5/20/2016.

Minimal impacts off southwest side of location. No apparent signs of spilled liquids.

No follow-up is necessary.